<u>Transcript for the Testing Wet Sensor Video</u>

Get started by making sure the wet sensor is properly inserted into the slot marked H next from the main screen on the control box select view and then click on BAT then increment to H to see the current value it should be 0 for non activated if the sensor reads 0 indicating it's dry go ahead and add some water to it so that we can test it directly and then watch the panel within one minute the 0 should turn to 1 if it's working properly.

Video demonstrator: Alex Tran (SSAI)
Video produced and narrated by Joel Schafer (SSAI)
Transcribed by Amy Scully (SSAI)